


230 Vac - 1 phase
voltage supply

Pe L1 L2

fuses*

⊕ -DC L1/L2/N L3



1 2 3 4 5 6 7 8 9 10 11

⊕ + BR U V W

M

